

Professional Series Portable Firmware Upgrade Kit R05.17.02 Customer Release Notes

NOTICE: The CPS PROGRAMMING DATA WILL BE LOST AFTER UPGRADING. PLEASE SAVE YOUR EXISTING CODEPLUG TO AN ARCHIVE FILE. It is recommended to save an archive of the radio's codeplug using CPS before the update process. After upgrading, this archive can be used to recover the CPS programming data of the radio.

Professional CPS R06.12.02 and later is recommended with this firmware.

This release of radio firmware only supports the Prime families of Professional Series Portable Radios. All bands in these families are supported. For any questions, please contact Customer Resources at 1-800-927-2744.

I. Enhancements

None

II. Corrections

Item #1: Radio Lock-Up

Fixed an issue where the radio could enter a state on power up where it would be unable to transmit. The issue occurred **ONLY** if a unit was powered up while one of the programmable side buttons was pressed or activated **and** an audio accessory was attached the unit. Some third party carrying cases were found to induce this issue, as they were too tight and depressed the side buttons. **Please note:** If the carrying case is causing side buttons to be actuated and is not corrected, the customer may report other symptoms.

III. Known Issues

None

MOTOROLA SOLUTIONS and the Stylized M Logo are registered in the U.S. Patent & Trademark Office.

All other product or service names are the property of their respective owners.

© Motorola Solutions, Inc. 2011.